

16 Battery Viscosity curve
(continuous test) Viscosity changes with
increasing shear rate
(take continuous
viscosity)

At room temperature, select the continuous test mode, take a small amount of slurry on the

